

Annual Report Attachment 2 – Post Audit Photographs

County Government Center – 701 Ocean Street



Photographs 1 and 2: Outside material storage cleaned up.

Annual Report Attachment 2 – Post Audit Photographs



Photographs 3 and 4: Cleaned storm drain inlets.

Annual Report Attachment 2 – Post Audit Photographs

Brommer Maintenance Yard – 2700 Brommer Street



Photographs 5 and 6: Outside material storage cleaned up.

Annual Report Attachment 2 – Post Audit Photographs



Photograph 7: Swale cleaned out.



Photograph 8: Downstream inlet.

Annual Report Attachment 2 – Post Audit Photographs



Photograph 9: Covered metal storage bin.



Photograph 10: Eastern boundary of maintenance yard, Rodeo Gulch riparian corridor behind fence. Perimeter controls installed.

Annual Report Attachment 2 – Post Audit Photographs

Lode Street Sanitation Facility – 2570 Lode Street



Photograph 11: Covered scrap metal bin.



Photograph 12: Marked storm drain inlet in the parking area.